

# Digital Weighing Indicator SI 300

# **Instruction Manual**





## CONTENTS

1.	Before Installation	 3 Page
2.	Introduction	 4 Page
3.	Specification	 5 Page
	3-1. Specification	 5 Page
	3-2. Front Panel	 6 Page
	3-3. Rear Panel	 8 Page
4.	Installation	 9 Page
	4-1. Dimension & Cutting Size	 9 Page
	4-2. Installation Components	 9 Page
	4-3. Load Cell Installation	 10 Page
5.	Set up	 11 Page
	5-1. Set Up mode	 11 Page
	5-2. TEST Weight Calibration Mode	 12 Page
	5-3. Simulating Calibration Mode	 16 Page
	5-4. F-FUNCTION Setting	 21 Page
	5-5. Test Mode	 28 Page
6.	Interface	 30 Page
	6-1. Serial Interface	 30 Page
	6-2. Serial Print	 40 Page
7.	Error & Treatment	 41 Page
	7-1. Load Cell Error & Treatment	 41 Page
	7-2. Calibration Error & Treatment	 42 Page
	7-3. Indicator Error & Treatment	 43 Page
Wa	arrantee Certificate	 44 Page

## **1. BEFORE INSTALLATION**

### **Caution / Warning Marks**

<b>A</b>	This mark warns the possibility to arrive death or serious injury
Warning	in case of wrongly used.
<b>A</b>	This mark cautions the possibility to arrive serious human body
	injury or product lose in case of wrongly used.

### **Copy Rights**

- 1. All Right and Authority for this Manual is belonged to SEWHA CNM CO., LTD.
- 2. Any kinds of copy or distribution without permission of SEWHA CNM CO., LTD. will be prohibited.
- 3. This manual may be changed as the version is upgraded, without previous notice.

#### Inquiries

If you have any kinds of inquiries for this model, please contact your local agent or Head Office.

Head Office : SEWHA CNM CO., LTD.

Website : http://www.sewhacnm.co.kr

Email : <u>sales@sewhacnm.co.kr</u>

## 2. INTRODUCTION

#### 2-1. Introduction

Thank you for your choice of this SI300 Industrial Digital Weighing Indicator.

This SI300 model is high-performance weighing Indicator.

Please review and learn this instruction Manual and enjoy your process efficiency

with "SI 300" Weighing Indicator.



- 1. Don't drop on the ground and avoid serious external damage on item.
- 2. Don't install under sunshine or heavy vibrated condition.
- 3. Don't install place where high voltage or heavy electric noise condition.
- 4. When you connect with other devices, please turn off the power of item.
- 5. Avoid from water damage.
- 6. For the improvement of function or performance, we can change item specification without previous notice or permission.
- 7. Item's performance will be up-dated continuously base on previous version's performance.

#### 2-3. Features

- 1. SI 300 model is the standard 1/8 DIN SIZE and compact enough, so it is easy to install.
- 2. It has wide range of DC Input.
- 3. Front panel is covered with Polycarbonate film, strong against dust and water.
- 4. RS-422/485 serial port standard installed,

## **3. SPECIFICATION**

### **3-1** Specification

	Content	Specification		
	Externa	l Resolution	1/20,000	
	Internal Resolution		1/2,097,152 (±1,048,576)	
	Input	Sensitivity	0.1µV/V	
	Max. Signa	l Input Voltage	3.2 mV/V	
	Load ce	ell Excitation	DC +5V	
Performance	A/D Conve	ersion Method	Sigma-Delta	
	Decir	mal Point	0, 0.0, 0.00, 0.000	
	Drift	Offset	10PPM/°C	
	Drift	Span	10PPM/°C	
	Lir	nearity	0.001% of Full Scale	
	Analogue Sampling(sec)		60times / sec	
Environment	Operating Temperature Range		-10°C ~ +40°C [14°F ~ 104°F]	
Linnonment	Operation Humidity Range		40% ~ 85% RH, Non-condensing	
	Calibration Mode		Test Weight Calibration Mode	
			Simulation Calibration Mode	
Function		licolay	7segment 6 digit, 1 inch	
	Display		Red Color FND	
	Ke	ey Pad	5EA Standard Key	
			Data Transference	
Comm	Serial	Interface	Command Mode	
			Serial Printer Mode	
Power	AC	FREE VOLTAGE ( AC	90 ~ 250V ) 50/60 Hz	
Size	190mm(W) x 124	4mm(H) x 122mm(D)	Weight : 2.0kg	

### 3-2. Front Panel

### 3-2-1 Front Panel (Display / Key Pad)



#### 3-2-2. State Lamp

STEADY	When the weight is "STEADY", Lamp is ON.
ZERO	When the current weight is "ZERO", Lamp is ON.
TARE	"TARE" function is set, Lamp is ON.
HOLD	"HOLD" function is set, Lamp is ON.
TxD	When the Indicator transmits Serial communication data (Print data),
	Lamp is ON.
RxD	When the Indicator receives Serial communication data, Lamp is ON.

#### 3-2-3. Key Operation

ZERO	<ol> <li>Normal Mode : Make Weight value as Zero. (F07, F08 setting)</li> <li>Calibration Mode : Cancel the value or move to previous step.</li> </ol>
	<ul> <li>1.Normal Mode : Set the TARE Function .(F09 setting)</li> <li>1<sup>st</sup> input : "TARE", 2<sup>nd</sup> input : "TARE Reset"</li> <li>(When "HOLD" or weight value is ZERO, then this key doesn't work.)</li> <li>2.Calibration Mode : Move to left</li> <li>3.F-Function setting : Move to left</li> <li>4.Test Mode 1 : Analog value check mode</li> </ul>
HOLD	<ol> <li>To set the "HOLD" Function (refer F10) [1<sup>st</sup> input : "HOLD", 2<sup>nd</sup> input : "HOLD Reset" ]</li> <li>Calibration Mode : Move to right</li> <li>F-Function setting : Move to right</li> <li>Under "SETUP" Mode, Enter into the "Calibration" Mode.</li> <li>Test Mode 1 : Analog Variation value check mode</li> </ol>
PRINT	<ol> <li>Normal Mode : Print out (refer F38, F32)</li> <li>Calibration Mode :Increase set value</li> <li>F-Function setting : Increase set value</li> <li>Set up Mode : Enter Test Mode.</li> <li>※ If the printer is installed, under "F01-01 setting, when you press this key the current valued is increased. And the current weight is saved and print out, altogether. (Refer to CH.5-4)</li> </ol>
F	1. Press this key 4times, within 2secs, enter "SET-UP" mode. 2.F-Function setting : Save the value go to next step

●Setup Mode :It is a mode can SET UP the calibration, Function of SI300 .(refer to CH5. SET UP) **3-2-4. Hot key (with F key)** 

G		Continuous "TARE" setting (From the second TARE setting, use this key)		
G		If the Printer is installed, You can print out the "Grand-total data". (GRAND-total data can be checked though Print output).		
G		Manual delete the grand total data		
Tip	Max. accumulated weighing count : 999,999times Over 999,999times → return to "0" time			
	Max. accumulated weight display : 999999999 (g, kg, ton)			
	Over 999,999,999 (g, kg, ton) → return to "0" (g, kg, ton)			

### 3-3. Connector






### 3-4. Composition

SI 300	AC Power Cable	Side Bolt	Terminal Pin	Manual
				EXAMPLE AND A STATEMENT OF A STATEME

## 4. INSTALLATION

### 4-1. External Dimension & Cutting Size

External Dimension (unit: mm)



### 4-2. Installation Components

SI300	Connector (3EA) 3P, 5P, 7P	Pin terminal(15EA)	User Manual

### 4-3 Load cell Installation

Load Cell Wire Connection (In case of SEWHACNM's Load cell) It depends on the manufacturer of load cell, please check the specification.



-----Sewhacnm Co., Itd. Load cell & wire color----

**\*** Load cell wire color can be changed without prior notice.



aution Under set up the Load cell, if EXC+ and EXC- have a short circuit,

It may cause damage in the indicator.(specially analogue board)

If you connect other wires to Load cell terminal wrongly, it may cause damage in the analogue board.

Before connecting the load cell cable you have to power off and be sure to connect the cable to the terminal correctly.

Do not weld near the load cells , Indicators or other devices.

### Load Cell Installation

- 1. You can connect Max. 8pcs of same capacity Load cells at once. (350  $\Omega)$
- 2. You have to make horizontal balance on the ground.
- 3. If you install more than 2pcs of load cells, use Summing box and adjust output signal difference as minimum. It can make wrong weighing process caused by each load cell's variation.
- 4. If there is some temperature difference around Load cell, it can cause wrong weight measurement.
- 5. Don't do Welding job or Arc discharge around installation place. But, there is no choice, please disconnect power cable and Load cell cable.
- 6. If you measure static electricity material, please make earth between down part and up part of Load cell.


## 5. SET-UP

### 5-1. Set up mode

This is the Menu which can set the all of the functions.

There may be some display differences between real and on the manual.

5-1-1. Start "SET UP" Mode (Pass Word Not use)










means SAVE/NEXT Step.

### Adjusting "ZERO" Balance (Calibration)

Adjust weight balance between "Real weight" on the load cell(Weight Part) and "Displayed weight of Indicator". When you replace LOAD CELL or Indicator, you have to Calibrate process once again.


(When you start calibration mode, TARE, HOLD & PRINT will be reset.)

Before processing calibration, please warm up the indicator during 15 min to guarantee more preciseness.




5-2 Test Weight Calibration Mode (Using test weight)

### 5-2-1. Start Test Weight Calibration Mode



 $\,\%\,$  If you set password through "F95", you have to input the pass word.

### 5-2-2. Setting "Capacity of weighing Scale"



**Tip** If you want that set Max capa is 1,000kg, then just input "1000".

#### Weight indicator SI 480E Weight indicator SI 480E Ο IU I $(\mathbf{F})$ HOLD After "DIVI" is displayed select Decimal point with key. HOLD Whenever pressing Vkey , decimal point will be changed. PRIN Please stop at the optimal position. And select Division optimal division with kev. key to save and move to next step. Finally press Tip Max. Decimal point will be 0.001, and digit can be selectable among 1, 2, 5, 10, 20, 50.


Digit and Decimal point must be fulfill the below condition.

- (Max. capacity value / division value) cannot be over than 20,000.

If this condition is not fulfilled, "Err - I" will be displayed and move back to Capacity setting mode.

### 5-2-3. "Decimal Point" and "Digit / Division" Value

14



#### 5-2-4. Measure the "DEAD" Weight of Weighing Scale.



Indicator will search "DEAE weight" during 10~20 secs automatically to find the best condition.


X Over than 1/10,000 resolution setting,

To guarantee the preciseness, DEAD weight calculation (CAL00~CAL09) will be operated twice.

**Tip** In this step, if there is some force or Vibration on scale part, these unstable conditions will be continued, "ErrorA" will be displayed, and "DEAD value" will not be calculated.

Under this condition, please remove the cause of force or vibration and process it again.

#### 5-2-5. Input Test Weight value and Calculate SPAN value.




### 5-3. Simulation Calibration Mode(Calibrate without Test weight)

With this "Simulation Calibration Mode" you can make simple calibration without any "TEST weight" This calibration mode uses "Load cells' max capacity" and "Max. Output Rate(mV)", so the weight adjustment degree might be less than "Test weight Calibration".


The guaranteed resolution of this "Simulation Calibration" is 1/3,000.


### 5-3-1. Simulation Calibration Mode Start

SI 300




### 5-3-2. Setting "Capacity of Load Cell"





### 5-3-4. Measure the "DEAD Weight" of Weighing Scale.





It takes 10sec or 20sec to get the best situation.

Over than 1/10,000 resolution setting,

To guarantee the preciseness, dead weight calculation will be operated twice.


### 5-3-5. Input Max. Output (Rated Output Voltage / mV)





If input wrong value, there will display "BAD", please go back to *Setting "Capacity of Load Cell".* After recheck the label of load cell and retry the process.

After displaying "mV", input Load cell Output Rate(mV), referring the load cell label. And press key to save.



**I** In case of plural piece of load cells are connected, the rated output will be same as single load cell's. (Because plural load cells are connected with parallel connection, the sum of rated output voltage is same as single load cell's rated output)

\*Due to some variation between **"State output rate"** and **"Real Output rate"** of load cell, there might be some weight difference after finishing calibration.

If you want to make more precise weighing process, please measure real output rate of load cell and input the measured value.


Then the weight measurement will be more precise than before.

### 5-4. F-FUNCTION Setting

SI 300

Set-up means set the F-function and make optimal operation of SI 300 controller.

### Starting F-FUNCTION Mode



### F-Function List

General Function Setting ("●" Factory default set value)

	Weighing Data Save Method selection					
F01		0	Non-Save Mode (Weight Data & weighing counter)			
FUI		1	Save Mode (Weight Data & weighing counter)			
			Weight –Back up selection			
F02		0	Normal Mode			
102	•	1	Weight Back up Mode			
			Motion Band Range setting			
		01	This is set "Steady" acceptable range of weighing part.			
F03	05	ſ	If there is vibration on weighing part, you can set this function and reduce			
FUS	05	99	the vibration effect on weighing process.			
		55	1 : Weak vibration ~~ 99 : Strong Vibration			
			Zero Tracking Compensation Range setting			
		00	Due to external causes (Temperature, wind, and dust), there will be small			
F04	05	ſ	weight difference, the Indicator will ignore the weight difference and			
		99	display as Zero.			
			Auto Zero Range setting			
		00	Within the "Auto Zero" range, weighing part is steady, indicator will display			
F05	00	ſ	current weight as "Zero"			
		00	99	If the weighing part is not "Steady", indicator will display current weight.		
		55	(Auto Zero Range : ± Set value + weight unit)			
	-		Digital Filter setting			
F06	04	0~40	0 (Weak vibration ) $\sim$ 40 (Strong Vibration)			
	-		Zero key Operation mode selection			
F07		0	Activate only under "Steady" condition			
107	•	1	Always activate			
		Zei	ro key Operation Range selection : (-) value is same to (+)			
		0	Activated within 2% of Max. Capacity			
F08		1	Activated within 5% of Max. Capacity			
FU0	•	2	Activated within 10% of Max. Capacity			
		3	Activated within 20% of Max. Capacity			
	•					

		4	Activated within 50% of Max. Capacity
		5	Activated within 100% of Max. Capacity
		6	There is no limit of Zero key operation range.
*			setting over than 10%, The display weight could be over than Load cell
			Max. Capacity and it may display "CELL-Err" or incorrect weight value.
	iput si	-	re key Operation Range selection : (-) value is same to (+)
		0	Activated within 10% of Max. Capacity
		1	Activated within 20% of Max. Capacity
F09		2	Activated within 50% of Max. Capacity
	•	2	
		5	Activated within 100% of Max. Capacity <b>"Hold" Mode selection</b>
<b>F10</b>	•	0	Peak Hold : Measure Max. weight value and hold on display.
F10		1	Sample Hold : Hold current weight until "Hold Reset"
		2	Average Hold : Hold average value (Refer F-F50)
	[	1	"STEADY" condition check time setting
	3	0	During the set time period, estimate weighing part's "STEADY" condition
F11		ſ	and display. If you set small value, indicator will take "STEADY" fast, if you
		9	set value, indicator will take "STEADY" slow.
			( 0.5sec per set value)
			Display Up-Date speed setting
	•	1	60/sec
		2	30/sec
		3	20/sec
		4	15/sec
F12		5	10/sec
		6	6/sec
		7	3/sec
		8	2/sec
		9	1/sec
		Wei	ght Display selection under "Unpass / OverLoad"condition
F13		0	Not Display Weight (just "UNPASS" or "–OL-" is displayed)
115	•	1	Display Weight (with a flash)

9

	Equipment No. setting – ID No.setting						
F18	01	01~99	ID No. setting with No. ke	ID No. setting with No. key. (01~99 settable)			
	Communication Mode Setting						
			Parity Bit se	election Mode			
		0	DATA Bit (8 Bit)	STOP Bit (1 Bit)	Parity Bit (Non)		
		1	DATA Bit (8 Bit)	STOP Bit (1 Bit)	Parity Bit (Odd)		
		2	DATA Bit (8 Bit)	STOP Bit (1 Bit)	Parity Bit (Even)		
		3	DATA Bit (8 Bit)	STOP Bit (2 Bit)	Parity Bit (Non)		
520		4	DATA Bit (8 Bit)	STOP Bit (2 Bit)	Parity Bit (Odd)		
F30		5	DATA Bit (8 Bit)	STOP Bit (2 Bit)	Parity Bit (Even)		
		6	DATA Bit (7 Bit)	STOP Bit (1 Bit)	Parity Bit (Odd)		
		7	DATA Bit (7 Bit)	STOP Bit (1 Bit)	Parity Bit (Even)		
		8	DATA Bit (7 Bit)	STOP Bit (2 Bit)	Parity Bit (Odd)		

#### Serial Communication Speed selection

STOP Bit (2 Bit)

Parity Bit (Even)

DATA Bit (7 Bit)

Serial Communication Speed selection						
		0	2,400bps			
		1	4,800bps			
	•	2	9,600bps			
		3	14,400bps			
F31		4	19,200bps			
F21		5	28,800bps			
		6	38,400bps			
		7	57,600bps			
		8	76,800bps			
		9	115,200bps			
			DATA Transference Method selection			
		0	Simplex Mode / Stream Mode			
F32	•	1	Duplex Mode / Command Mode			
		2	Print Mode			
	"Check-Sum" detection selection (Under F32-01 setting, only)					
F34		0	Check-Sum Not Use			
F34		1	Check-Sum Use			
	Under Stream Mode select the way transmit data protocol/frame (basic port)					


525	•	0	Transmit by Protocol
F35		1	Transmit by frame (in case of using specific utility)
Cautio	on : In	case o	of "Transmit by frame" & under 14,400bps setting(F31), the speed of
syster	m will b	e slow	
		DATA	A Transference Mode selection (Under F32-00 setting, only)
	●	0	Always
		1	Single time data transference, Whenever the weight is steady over Empty
F36		Ŧ	range.
		2	Single time data transference, at first steady point, over Empty range.
		3	Data transference, Whenever "Print" key input
		DATA	Transference Format selection (Under F32-00 setting, only)
	●	0	Format 1 (recommended when use external display)
F37		1	Format 2. (Format 1 + ID No.)
137		2	Format 3. (recommended when connecting to PLC or PC)
		3	CAS Format
			Print Mode selection (Under F32-02 setting, only)
	•	0	Manual Print : Whenever "Print" key input.
		1	Auto print (at the first Steady point over "EMPTY" range
F38		L L	or Whenever "Print" key input.)
		2	Auto print (Whenever Steady status at over "EMPTY" range
		2	or Whenever "Print" key input.)


### Print Mode Setting

			Weight Unit selection
	•	0	Kg
F41		1	g
		2	t
			Print Format selection
F42	•	0	Continuous Print - Serial No. and Weight will be printed continuously.
F42		1	Single Print - Date, Time, S/N, ID No. Weighing Data will be print
			SUB/GRAND Total Data Delete selection
F44	•	0	Not deleted (= manual Delete mode)
Г44		1	Automatically DeletedAfter print out SBU/GRAND Total.

		Р	aper Withdraw Rate setting (After SUB/GRAND Total Print)					
F45	3	0~9	Whenever set value increased as 1, then 1 line will be added.					
		Р	aper Withdraw Rate setting (After Continuous/Single Print)					
F46	<b>F46</b> 3 0~9 Whenever set value increased as 1, then will be added.							
	Printing Language Selection							
F47	۲	0	KOREAN					
Г47		1	ENGLISH					
			Minus(-) symbol Print selection					
F40	۲	0	Print minus(-) symbol, if the weight is minus(-).					
F49		1	Ignore minus(-) symbol					
			Set time of "Average Hold"					
F50	3	0~9	When setting "Average Hold", set the time. (unit : sec) XAutomatic Hold Rest , After set time.					


#### Other Setting Mode






Tip If there is no change although pressing keys or loading some force on/in weighing part, it may something wrong with load cell, cable, connector or A/D board

### 5-5-1. Analog Check Mode



### 5-5-2. Analogue Value Check Mode



Under this mode, you can check the variation degree of analogue value .













Displaying 10~1,000,000 Displaying 100~10,000,000


### 5-5-3. Key / Digital input Test Mode



Under this mode, you can test Key input and Digital Key input test

Whenever pressing key pad or plus to digital input terminal, the matched No. will be displayed on the each position.





First display position is for key pad input


Second display position is for digital input

### 4) Serial Interface Test Mode.



Connect with PC or other devices through serial interface and check the transference and receipt. At the normal operation, display will be blinked. **To test this mode, please use "TESTING Protocol".** 

### **\* TESTING PROTOCOL.**



※ If you send "Testing protocol" from PC to Indicator, at the normal operation Display will blink.

## **6.** INTERFACE

### 6-1. Serial Interface

### 6-1-1. Serial Interface (RS-232C)



RxD	- 3
TxD	2
GND	5



### 6-1-2. Current Loop





Serial communication interface is sensitive to electric noise. Install isolated place from Power cable or other electric cables and wires, and please use shielded cable for better performance.

### 6-1-4. Data Format

1. Data Format1 : ID Number is not be transferred.(Refer "FUNCTION 37/F67-00" setting)

Header 1	Header 2	Data Byte 7 byte Unit	t		
,	+	·I_ // K	g	CR	LF
	Header1	Header2			
	OL : OVER LOAD	NT : NET-WEIGHT(Tare is not set)	_		
	ST : STEADY	GS : when setting TARE	_		
-	US : UNSTEADY		_		

2. Data Format2 : ID Number + Data Transference (Refer F-function 37-01, F18)

ID Number	Header 1	Header 2	Data Byte 7 byte	Uni	it	
,	9	,	+/_	k	g C	R LF
			1/			

Header1	Header2
OL : OVER LOAD	NT : NET-WEIGHT(Tare is not set)
ST : STEADY	GS : when setting TARE
US : UNSTEADY	

#### 3. Data Format3 : ID Number + State (F37-03 setting)

U : UNSTABLE

STX	ID N	lumber	State 1		xed b	yte	Data E 7 byi	Byte te	_	ecim Point	al ETX
02h					"W"	+/_			"P"		03h
								Fi	と xed by	/te	
		н	eade	r1			Heade	r2			
		0	: OV	ER		G	: Gross v	weight			
	-	S :	STEA	DY			N : Net w	eight			

SI 300


Header 1	l Head		ID mber	Data E 8 by:	Byte <sup>te</sup> Space	e Un	it		
	3	9		, //		k	g	CR	LF
LAMP DIS	<b>SPLAY</b>		Lamp Display						
Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit	1	E	Bit O
1	0	1	1	1	1	1			1
1	STEADY	1	Hold	Print	Gross Weight	TAI	RE	Z	ero
			_						

### 4. CAS Format (22byte)

Header1	Header2
OL : OVER LOAD	NT : GROSS weight
ST : STEADY	GS : Net weight
US : UNSTEADY	

### 6-1-5. Command Mode (F32-01 setting)

Under "Command Mode", Indicator will recognize the receipt of Order based on 02h(Header) and 03h(END) signal, and transfers ACK/ NAK).



\*\*Although wrong value is transmitted, the communication format is matched, then ACK is transmitted.

### **Read Command**

	1.Current Weig	Jht data
ASCII : STX ID(2Byte	e) RCWT ETX	HEX: 02 30 31 52 43 57 54 03
	STX ID RCWT State1(1byte)	State2(1byte) P decimal point(1byte)
	+/-(1byte) Current weight(	7byte) unit(2byte) ETX
SI 300 response	State1 : O(Over load) , S(St	eady), U(Unsteady)
	State2 : N(Net weight), G(C	Gross weight), P+No. : decimal point
	number	
Ex) Steady(S), TARE	not used(N), 0.000kg	
	State1, State2, Decima	al point
STX ID R C 02h 30h 31h 52h 43	W T S N P 3 + Sh 57h 54h 53h 4Eh 50h 33h 2Bh	0 0 0 0 0 0 0 0 k g ETX 30h 30h 30h 30h 30h 30h 6Bh 67h 03h
	2. Indicator men	nory data
ASCII : STX ID(2Byte	e) RCWD ETX	HEX: 02 30 31 52 43 57 44 03
	STX ID RCWD P decimal po	int(1byte)DATE(6byte) TIME(6byte) the
SI 300 response	no. of weighing (6byte) +/	<pre>/- TARE(7Byte) +/- current</pre>
	weight(7byte) unit(2byte)	ETX
Ex) DATE : Aug 12 <sup>th</sup> ,	.2009, TIME : 12:00:00, the no	. of weighing : 10, TARE : 2.000kg, current
weight : 3.000kg		
	decimal point	
STX ID. R	C W D P 3 0 9 0	0 8 1 2 1 2 0 0 0 0
02h 30h 31h 52h 4	13h 57h 44h 50h 33h 30h 39h 30	0h 38h 31h 32h 31h 31h 30h 30h 30h 30h
	0 + 0 0 0 2 0 0	0 + 0 0 0 3 0 0 ETX
30h 30h 30h 30h 31h	30h 2Bh 30h 30h 30h 32h 30h 30l	h 30h 2Bh 32h 30h 30h 33h 30h 30h 30h 03h
	3. Grand Tota	al data
ASCII : STX ID(2Byte	e) RGRD ETX	HEX: 02 30 31 52 43 57 44 03
SI 300 response	STX ID RGRD P decimal po	int(1byte) the no. of weighing (6byte)
51 500 response	Accumulated weight(10by	te) unit(2byte) ETX
Ex) the no. of weigh	ning : 10 , Accumulated Weig	ght : 10.000kg
	decimal point	
STX ID R G 02h 30h 31h 52h 47h	R D P 3 0 0 0 0 52h 44h 50h 33h 30h 30h 30h 30h 3	1 0 0 0 0 0 1 0 0 0 0 ETX 1h 30h 30h 30h 30h 31h 30h 30h 30h 30h 03h


					4.	Finis	hed	Weig	ght o	lata						
ASCII : ST	TX ID	(2Byt	e) RF	IN ET	<				HE	<b>X:</b> 0	2 30	31 5	52 46	5 49	4E (	)3
SI 300 re	spon	se	STX	ID RF	IN P	deci	mal	poin	t(1b	yte)	+/-	Fini	shec	l we	ight	(7byte)
							ETX									
Ex) Finish	ed we	eight	: 2.0	00kg		dec	imal	poir	t							
STX	ID	R	F	I N	P			0	0	0	2	о	о	о	ET	x
02h 30h		52h	46h 4			<u> </u>		1								
					5.		urren			]	]		]			]
ASCII : ST	חז אד	′2B\/t			_						0 31	52	51 1		03	
SI 300 res		. ,	-	RTIM		nt Tir	ne <b>(6</b>			02 3	0 51	JZ	54 4	940	05	
Ex) Time : 1	•				Curre	111 111		Syle)								
EX) TITLE . I	.2.00.00		ID	R	- ,	м		2	0	•	•	•				
				к 52h 54	1 1 11 49				0 30h	0 30h	0 30h	0 30h	ETX 03h	2		
				020												
		(0.0	<u> </u>			o. Cu	rren									
ASCII : ST										02	30 33	1 52	44 4	11 54	4 03	
<b>SI 300 res</b> Ex) Date : A	•			RDAT	Curre	nt Da	ate <b>(6</b>	byte)	EIX							
EX) Date . A														,		
	STX		D	R D	A	Τ	0	9	0	8	1	2	ET)	(`		
		204	244	FO4 44		EAL	-	1	-	-	~	001	0.01			
		30h	31h	52h 41	h 41)		30h	39h	30h	-	31h	32h	03h			
		30h	31h	52h 41	h 411		-	39h	30h	-	31h	32h	03h			
ASCII : S	02h						30h	39h re da	30h Ita	38h	<b>31h</b> 30 32	][		41 52	2 03	
<b>ASCII :</b> S <sup>-</sup> SI 300 res	<b>02h</b> TX ID(	2Byt	e) RT		X	7	30h 7. Tai	39h re da H	30h Ita EX :	<b>38h</b>	30 3:	1 52	54 4			e) ETX
	02h TX ID( ponse	(2Byt	e) RT	AR ET	X P dec	7 cimal	30h 7. Tai	39h re da H t(1by	30h Ita EX :	<b>38h</b>	30 3:	1 52	54 4			e) ETX
SI 300 res	02h TX ID( ponse	2Byt	e) RT	AR ET	X P dec	7 cimal	30 <i>h</i> 7. Tai poin	39h re da H t(1by	30h Ita EX :	<b>38h</b>	30 3:	1 52	54 4			e) ETX ETX

Recommended Interval of READ COMMAND is min.60ms, 70ms is recommended, under 9600bps setting. Min.60ms is required between each Read Command(under RCWD) Min. interval is changed when data's length & speed are changed. Min Interval : 20ms under 2400bps(RCWD) Min Interval : 40ms under 115200bps (RCWD)

### SI 300

### ■Write Command

	Zero (same as "ZERO" key)			
ASCII : STX ID(2Byte)	ASCII : STX ID(2Byte) WZER ETX HEX: 02 30 31 57 5A 45 52 03			
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
	TARE			
ASCII : STX ID(2Byte)	ASCII : STX ID(2Byte) WTAR ETX HEX: 02 30 31 57 54 41 52 03			
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
	TARE rese	t		
ASCII : STX ID(2Byte)	) WTRS ETX	HEX: 02 30 31 57 54 52 53 03		
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
	HOLD			
ASCII : STX ID(2Byte)	) WHOL ETX	HEX: 02 30 31 57 48 4F 4C 03		
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
	HOLD rese	et		
ASCII : STX ID(2Byte)	) WHRS ETX	HEX: 02 30 31 57 48 52 53 03		
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
	PRINT			
When transfer for	ormat, "F46 : plus line" and	"F34 : checksums are not applied.		
ASCII : STX ID(2Byte)	) WPRT ETX	HEX: 02 30 31 57 50 52 54 03		
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
	PRINT grand	total		
ASCII : STX ID(2Byte)	) WGPR ETX	HEX: 02 30 31 57 47 50 52 03		
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
	Delete grand total			
ASCII : STX ID(2Byte)	WGTC ETX	HEX: 02 30 31 57 47 54 43 03		
SI 300 response	normal: STX ID ACK ETX	rror: STX ID NAK ETX		
Date setting				
ASCII : STX ID(2Byte) WDAT current DATE (6byte) ETX				
Ex) Date : Aug 12 <sup>th</sup> ,2009				
STX ID	STX ID W D A T 0 9 0 8 1 2 ETX			
02h 30h	31h 57h 44h 41h 54h 30h 3	39h 30h 38h 31h 32h 03h		
SI 300 response	normal: STX ID ACK ETX e	rror: STX ID NAK ETX		




Recommended Comm. Interval of WRITE COMMAND is Min. 100ms. Comm. Interval of WPRT is Min.300ms You have to guarantee Min. 100ms interval between two different commands. Response for WPRT will be output through Print Port, set by F32-0.

### ■ Command Mode Example


### READ COMMAND

SI 300

Ex.) Current Weight Command(RCWT), ID No.: 01, Current Weight: 7,000kgP.C Read Command Format (STX ID NO. RCWT ETX) "Check-sum" not used.



2) When PC requests to Indicator, Format(STX ID RCWT ETX) CHCEK SUM is used.




Incorrect operation

#### WRITE COMMAND Ex) SP1 Setting Command, ID No: 01, New SP1 Set value: 0.600kg 1) PC Write command format (STX ID WPR1 000.600 ETX) "CHECK SUM" not use. PC transmits to SI300 STX ID 2 w Т м 1 0 0 0 0 I ETX 31h 57h 54h 49h 4Dh 31h 32h 30h 30h 30h 02h 30h 30h 03h SI300 **Response to PC** STX ID ACK STX ID NAK ETX ETX 02h 30h 31h 15h 03h 02h 30h 31h 06h 03h

SI 300

1) PC Write command format (STX ID WPR1 000.600 ETX) "CHECK SUM" use.

Normal operation



### 6-2 Serial Print (F32-02 setting) – RS-232 Serial Interface.

It can be connected with all kinds of Serial interface printer, but the printing format is already programmed and fixed with SE7200/7300 model.

### 6-2-1. Printing Format

Using the RS-485 or 422 interface, please use convertor and converts to RS-232 and connect with Serial printer.

If you use RS-232 serial interface, connect directly without any convertor.

#### English Format (F47-01)

==================			
DATE :	2009-05-10		
TIME :	18:00:10		
COUNT	WEIGHT		
1	+ 1.330kg		
2	+ 5.350kg		
3	+ 1.380kg		
4	+ 2.330kg		

DATE :	2009-05-10		
TIME :	18:00:10		
COUNT	WEIGHT		
2	+ 5.350kg		
DATE :	2009-05-10		
TIME :	18:00:10		
COUNT	WEIGHT		
3	+ 1.280kg		

#### Single Print Format(F42-01)

TOTAL	
DATE : TIME : COUNT : TOTAL WEIGHT :	2009-05-10 18:00:10 10
TOTAL WEIGHT : ====================================	258.145kg ======= ETE

Grand Total Print

(Grand Total Print delete setting, F44-01)

40

## 7. Error & Treatment

### 7-1. Load Cell Installation

Error	Cause	Treatment	Remarks
	1) Load cell broken		1) Input Resistance of
	2) Load cell isolation	1) Measure	"EX+" and "EX-" is
	resistance error	input/output resistance	about 350Ω~450Ω.
Weight Value is	3) Weighing part touches	of Load cell.	2). Output Resistance
unstable	other devices or some		of "EX-" and "EX+" is
	weight is on the weighing	2) Measure Load cell	about 350Ω.
	part	isolation resistance	3). Isolate Resistance
	4) Summing Board Error		is more than $100\Omega$
Weight Value is		1) Check Load cell	
increased regular	1) Load cell Error	connection	
rate, but not	2) Load cell connection Error	2) Measure Load cell	
return to "Zero"		Resistance	
Weight Value is increased to under Zero	Load cell Output wire (SIG+, SIG-) is switched	Make wire correction	
"UN PASS"	Load cell broken or Indicator connection Error	Load cell Check Load cell connection Check	
display	Power was "ON" when some weight is on the load cell.	Remove weight on the Load cell	
"OL" or "UL" display(Over Load)	<ol> <li>Load cell broken or</li> <li>Indicator connection Error</li> <li>Loading over than Max.</li> <li>Capacity</li> </ol>	<ol> <li>Load cell Check</li> <li>Load cell connection</li> <li>Check</li> <li>Remove over loaded</li> <li>weight</li> </ol>	

### 7-2. Calibration Process

Display	Cause	Treatment		
	When Max.capacity/digit value is over	Re-input the Max. Capacity, less than		
ErrOl	20,000	20.00		
	20,000	(Max. Capacity / Digit)		
ErrO4	Standard weight value is over than Max.	Re-input Standard weight value with		
	Capacity	Number keys, under Max. Capacity		
	Standard weight value is less than 10% of	Re-input Standard weight value with		
ErrOS	Max. Capacity	Number keys, more than 10% of Max.		
		Capacity		
		Check standard weight's weight with set		
	1. Amp. Gain is too big	value.		
Err06	2. Sig+ and Sig- wire connection error	If there is difference between set value and real weight, please re-input the value		
	3. Test weight is not loaded			
		(set value is too small)		
		Check standard weight's weight with set		
	1. Amp. Gain is too small	value.		
ErrO7	2. Sig+ and Sig- wire connection error	If there is difference between set value		
	3. Test weight is not loaded	and real weight, please re-input the value		
		(set value is too big)		
Err08	Under "F-function" model, set value is	Check the correct value and re-input		
	"N.A"			
	When there is continuous vibration on the	- Find vibration cause and remove		
Err-R	weighing part,, indicator cannot process	- Load cell check		
	calibration any more.	- Load cell cable and connecting		
		condition check		

Display	Cause	Treatment	
"EELL- Er" or "OUEr"	<ol> <li>Load cell Error</li> <li>Load cell cable Error</li> <li>Load cell connection Error</li> <li>A/D Board Error</li> <li>If Analogue value         <ul> <li>is over 1,040,000.</li> <li>When weigh "-" value,</li> <li>If it is over set max capa, "OVER"                  is displayed.</li> <li>Ex) Even though set max capa is                  "100" and it is over "-100",                  "OVER" is displayed.</li> </ul> </li> </ol>	<ol> <li>Under "TEST" mode 1, check analogue value. If you cannot get any analogue value or there is no change although adding load, please check load cell, load cell cable, connection conditions first.</li> <li>Replace another load cell, and check the indicator condition. If you have same problem, please replace new indicator and check A/D board error.</li> <li>Try to connect the indicator's A/D with the other indicator.</li> <li>Check the power and connection of terminal.</li> </ol>	
"UNPASS"	<ol> <li>Power is ON, when some materials are on weighing part.</li> <li>Wunder "Normal Mode", if there are more than 20% loading of Max. capacity, "Un-Pass" display will be appeared and indicator will stay until removing the load.</li> <li>Setting Back-up mode it can memory empty value, and it becomes set value without displaying" Un-pass")</li> </ol>	<ol> <li>If you set "Normal Mode", please check weighing part empty or not before turn on the power. If there are some materials in/on weighing part, please remove those materials and turn on the power.</li> <li>Please try to set F02-01(Back-up) mode so that the indicator can remember first empty value.</li> </ol>	
"SEL"	When Power is on, "SET" displays. It means EEPROM has some problem.	Please contact the distributor or Head	
"HALE"	H/W has some problem.	Office.	
"Ł-Err"	The dead Battery		

### 7-3. Digital Weighing Indicator

\* Under **"[ELL-Er"**, Zero key, Tare key, Hold key and print key will not be activated.

#### WARRANTEE CETIFICATION

This product is passed "Sewhacnm's strict quality test.

If there is defect of manufacturing or abnormal detection within warrantee period,

please contact our Agent or Distributor with this Warrantee certificate.

Then, we will repair or replace free of charge.

#### WARRANTEE CLAUSE

# 1. The Warrantee period, we can guarantee, is one(1) year from your purchasing date

#### 2. Warrantee Exception Clause

- Warrantee period is expired.
- Any kinds of Mal-function or defection caused by Modification or Repair without Sewhacnm's permission.
- Any kinds of Mal-function, Defection, or External damage, caused by operator
- Any kinds of Mal-function, Defection, caused by using spare part from Non-Authorized Distributor or Agent.
- Any kinds of Mal-function, Defection, caused by not following Warnings or Cautions mentioned on this manual.
- Any kinds of Mal-function, Defection caused by "Force Majeur", like Fire, Flood.
- Without presentation of this "Warrantee Certification".

#### 3. Other

- Any kinds of "Warrantee Certification" without authorized Stamp is out of validity

SEWHACNM Co.,Ltd.	Product	Digital Weighing Indicator	
302, 102dong, Ssangyong 3 <sup>rd</sup> , Bucheon	Model	SI 300	
Techno Park, Seokcheon-ro397beon-gil,	Serial No.		
Ojeong-Gu, Bucheon City, GyungGi-Do,	AUTHORIZED STAMP		
KOREA			
Made in KOREA			
Website : <u>http://www.sewhacnm.co.kr</u> ,			
Email : sales@sewhacnm.co.kr			